





The brazed seam will not separate under pressure of operating stress.  
 A funnel entry nylon insulator allows easy wire insertion.



### Rings

Wire Size	Stud Size	Part No.	
22-18	6	50020BZN+	
	8	50030BZN+	
	10	50040BZN+	
	6-8-10	50040MBZN	
	1/4	50041BZN+	
	5/16	50042BZN+	
3/8	50043BZN+		
.....			
16-14	6	50086BZN+	
	8	50090BZN+	
	10	50100BZN+	
	6-8-10	50100MBZN	
	1/4	50101BZN+	
	5/16	50102BZN+	
	3/8	50103BZN+	
	1/2	50104BZN+	
.....			
12-10	6	50210BZN+	
	8	50220BZN+	
	10	50230BZN+	
	6-8-10	50230MBZN	
	1/4	50240BZN+	
	5/16	50250BZN+	
	3/8	50260BZN+	
1/2	50233BZN+		




### Multi Stud Ring

22-18	6-8-10	50040MBZN	
.....			
16-14	6-8-10	50100MBZN	
.....			
12-10	6-8-10	50230MBZN	




### Male Quick Disconnects

22-18	.250 x .032	50177BZN	
.....			
16-14	.250 x .032	50181BZN	
.....			
12-10	.250 x .032	50186BZN	




### Spades

Wire Size	Stud Size	Part No.	
22-18	6	50050BZN+	
	8	50060BZN+	
	10	50070BZN+	
.....			
16-14	6	50140BZN+	
	8	50150BZN+	
	10	50160BZN+	
.....			
12-10	6	50270BZN+	
	8	50280BZN+	
	10	50290BZN+	

### Snap Spades

22-18	6	50051BZN+	
	8	50061BZN+	
	10	50071BZN+	
.....			
16-14	6	50141BZN+	
	8	50151BZN+	
	10	50161BZN+	
.....			
12-10	6	50271BZN+	
	8	50281BZN+	
	10	50291BZN+	
	1/4	50241BZN+	

### Block Spades

22-18	6	50052BZN+	
	8	50062BZN+	
	10	50072BZN+	
.....			
16-14	6	50142BZN+	
	8	50152BZN+	
	10	50162BZN+	
.....			
12-10	6	50272BZN+	
	8	50282BZN+	
	10	50292BZN+	

Nylon Insulated Brazed Barrel